




WarmMark QR - Cloud User Manual

New User Set Up


Each bag of WarmMark QR has a registration code on the bag label. Users can either scan the QR code or follow the link to register for their cloud account.

Scan QR code or follow link




Create Account

One person per organization should create an account from the bag label. That person can then add users to the account with various permissions. The sensors are unique to the cloud which they are added to so it is important to have all persons who need access within the same cloud. An email will be sent to the user with a temporary password.



Login with Temporary Password


Users can log in at <https://qr.spotsee.io>



The image shows the SpotSee login interface. At the top left is the SpotSee logo. In the top right corner, there is a blue button with a person icon and the text "SIGN IN". Below this is a white login form with a blue border. The form contains a "Username" field with a person icon, a "Password" field with a lock icon, and a "Reset Password?" link. There is a "Remember Me" checkbox and a blue "Sign In" button. At the bottom of the form, it says "© Copyright 2024-11-04. All Rights Reserved."

Finish Profile and Password Set Up


After logging in with the temporary password, the user will be prompted to change their password. Each user must have a unique username and a password that meets system requirements.



The image shows the "Update Profile" form. At the top left, it says "Update Profile". Below this is a red banner with the text "Please set your password to proceed". The form contains several fields: "Username" with a person icon, "Full Name" with a pencil icon, "Email" with an envelope icon, "Temperature Scale" with a dropdown menu set to "Celsius (°C)", "Date Format" with a dropdown menu set to "mm/dd/yyyy (04/04/2024)", and "Time Zone" with a dropdown menu set to "(UTC -05:00) Eastern Time (US & Canada), Bogota, Lima". There is a checkbox for "Update Password?" which is checked. Below this is a "Password" field with a lock icon and a "Generate Password" button. At the bottom, there is a note: "Minimum eight (8) characters in length, at least two (2) complexity controls (uppercase letter, lowercase letter, special character), no reuse of previous six (6) passwords".

Returning User Sign On


After a username and password have been established, users can sign in by navigating to <https://qr.spotsee.io> and signing in.



The image shows the SpotSee login interface. At the top left is the SpotSee logo. In the top right corner, there is a blue button labeled 'SIGN IN' with a user icon. Below this is a white login form with the following elements: a 'Username' label above a text input field with a user icon; a 'Password' label above a text input field with a lock icon and a 'Reset Password?' link; a 'Remember Me' checkbox; and a blue 'Sign In' button. At the bottom of the form, there is a copyright notice: '© Copyright 2024-11-04. All Rights Reserved.'


Dashboard

Upon signing in, users will access their Dashboard which provides an overview of the Sensors Scanned, Excursions Detected, Sensors Remaining, Allocated Shipments, temperature excursion heat map and WarmMark Shipments scan data by month.



Navigation Bar

When the cursor is positioned over the left side of the **Dashboard**, the **Navigation Bar** will appear. This menu allows the user to choose the appropriate views for information like the Dashboard (Home), WarmMark Shipments, and Admin, consisting of Users and Audit Log.



WarmMark Shipments


By using the **Navigation Bar** to enter the **WarmMark Shipments** screen, the user will display summary information for each of their sensors.

Product	Sensor I.D.	Shipment I.D.	Shipment Condition	Sensor Image	Location	Last Scan	Time Zone	History
WarmMark	22223WTVFKAA84	EQ	✓	View Image	View Map	2024-09-27 14:17:09	America/Lima	History
WarmMark	22223WTV78CH67	EQ	✗	View Image	View Map	2024-09-25 10:33:28	America/Lima	History
WarmMark	22223WTVM3727D	EQ	✓	View Image	View Map	2024-09-25 10:52:37	America/Lima	History
WarmMark	22223WTVY7AV8J	EQ	✗	View Image	View Map	2024-09-25 10:26:02	America/New_York	History
WarmMark	22223WTVN47V6C	EQ	✓	View Image	View Map	2024-09-25 10:03:49		History
WarmMark	22223WTVCY86EV	EQ	✓	View Image	View Map	2024-09-25 06:55:06		History

Below are definitions for the fields and buttons found on the WarmMark Shipments screen:

Sensor I.D.: Unique identification code for a particular WarmMark sensor. This can be found by scanning the QR code on the front of a sensor.

Shipment I.D.: User fillable field for inserting an order number, tracking information, or other identifying descriptor that a shipper can use to tie to a sensor I.D. Click icon to bring up fillable window.



Shipment Condition: Condition read-out status based on the last scan:



No condition recorded



Shipment OK, no temperature excursion detected




Temperature Excursion Detected

Sensor Image: Image of the last scan taken... this is what the end user saw. Clicking on the **View Image** text will open a separate browser window displaying the image.



Location: Location of last scan based on scanning device (cell phone) connectivity. Clicking on the **View Map** text will open a separate browser window displaying the map.



Last Scan: Time and date stamp of last scan.

Time Zone: Time zone of the last scan.

History: By clicking on the **below icon under the History column** users can view detailed scan history for specific sensors. Information available includes condition, a scan image, location, time and date, and time zone of a particular sensor I.D.

Scan History 22223WTS8D8M37

#	Shipment Condition	Sensor Image	Location	Scan Date	Time Zone
5	✓	View Image	View Map	2024-10-20 19:40:52	
4	✓	View Image	View Map	2024-10-20 17:04:31	2024-10-20 12:04:51 (America/Chicago)
3	✓	View Image	View Map	2024-10-20 16:10:49	
2	✓	View Image		2024-09-23 17:43:57	
1	✓	View Image	View Map	2024-09-23 17:40:10	2024-09-23 13:40:15 (America/New_York)

Map Satellite

Google

Keyboard shortcuts | Map data ©2024 Google, INEGI | Terms

CLOSE

Adding Sensors to Cloud

When first receiving WarmMark QR sensors, locate the bag label on each 100 pack.



Mobile Phone:


- Scan the QR code with your mobile device
- Log in to, or register for, a SpotSee cloud account
- Navigate to the WarmMark Shipments page, and select **Add Sensors** located in the top right corner
- When added with mobile device via QR code on bag label, bag IDs will automatically populate into cloud



Computer:

- Log in to, or register for, a SpotSee cloud account
- Navigate to the WarmMark Shipments page, and select **Add Sensors** located in the top right corner
- Type or scan the bag ID(s) associated with the bags of sensors you need to add to your cloud






Adding A User

Hover over the **Navigation Bar** to display the Admin selection. Select the **drop down on the Admin selection** to make visible Users and Audit Log. Select **Users**.

All Active Users and Removed Users are displayed on this page. Select **+Add User** in the top right corner to begin steps of adding a new user.



After completing the required fillable fields, select the **User Role** for the new user.

User Role:

- USER_ADMIN:** Full access to system
- USER:** Limited access (unable to manage users/api users or view audit log)
- API_USER:** API access only

Audit Log

Hover over the **Navigation Bar** to display the Admin selection. Select the **drop down on the Admin selection** to make visible Users and Audit Log. Select **Audit Log**.

The screenshot shows the 'Audit Log' page with a search bar and a table of records. The table has columns for Name, Section, Action, Data, and Audit Date.


Name	Section	Action	Data	Audit Date
Mason McWilliams	Reporting	Create	ReportType: Sensors, BagID: 0, Status: -1, ProductCode: , DateRange: 2024-10-04 00:00:00-2024-11-04 ...	2024-11-04 14:26:58
Mason McWilliams	QRShipment	Create	SensorID: 22223WTVJ9A846, ShipmentID: Order#378HXW9	2024-11-04 14:13:40
Mason McWilliams	Reporting	Create	ReportType: Shipments, DateRange: 2024-01-01 00:00:00-2024-10-31 23:59:59	2024-10-31 13:48:45
Mason McWilliams	Reporting	Create	ReportType: SensorHistory, SensorID: 22223WTVK9C24R	2024-10-30 14:11:22
Mason McWilliams	QRBag	Create	Allocate Bag, ID: 222222BpR4H8GT	2024-10-30 14:08:26
Mason McWilliams	Users	Modify	Username: TWilliams -> TWilliams, Full Name: Tim -> Tim Williams, Email: twilliams@spotsee.io -> twi...	2024-10-28 20:46:43
Mason McWilliams	Users	Create	Username: TWilliams, Full Name: Tim, Email: twilliams@spotsee.io, Temperature Scale: C, Date Format:...	2024-10-28 20:46:34

The Audit Log captures the creation, deletion, and modification of records within the SpotSee Cloud.

Exporting Data

Located throughout the cloud are various opportunities to export data including the Dashboard (Home), WarmMark Shipments page, within the modal window on the scan history column, and the audit log.

Look for these icons:



Report Requested

Your report has been created, please click the link below to download your report

Download Report

OK